


Typical Wiring Diagrams


Always use wiring diagram supplied on motor nameplate

CONNECTION DIAGRAMS

WEG Three Phase Motors
460 Volts / 12 Lead / Part Winding
(#Co4-460-12 Leads Part Winding)





* Reduced Voltage Auto Transformer



NOTE: Always check motor name plate for the correct wiring diagram for that motor.

CONNECTION DIAGRAMS

WEG Three Phase Motors




Typical Wiring Diagrams

Always use wiring diagram supplied on motor nameplate


Single-Phase Motors

With Thermal Overload Protection


Dual Voltage / Reversible Rotation




Dual Voltage / Single Rotation



Single Voltage / Reversible Rotation




Single Voltage / Single Rotation



Without Thermal Overload Protection


Dual Voltage / Reversible Rotation



Dual Voltage / Single Rotation



Single Voltage / Reversible Rotation



Single Voltage / Single Rotation

